



4.5 Electromagnetic Induction





* Emf (electro motive force) is induced whenever a conductor cuts magnetic field lines.


* $\text{Emf} \propto \text{rate of cutting the field lines.}$



Motor effect




Fleming's right-hand rule



* emf is induced when there is a change in field lines enclosed by loop.
 * the magnitude of induced emf $\propto$ the rate of change of enclosed field lines.
 (Faraday's Law)

Lenz's Law

* An induced current always flow in a direction oppose to the change it produces



pushing a magnet







pulling a magnet

Follows the right-hand grip rule

* If you try to change the number of enclosed fields, The loop responds by sending a current that counters your effort.

Applications of EM induction




How to raise the output voltage

1. Use stronger magnet
2. Wind more turns
3. Add a soft iron core
4. Increase the area of coil
5. Rotate the coil more quickly


Eddy Current Applications

Electric Brakes

If a metal plate moves
Eddy Current forms on plate surface
Such Current opposes the motion



Induction Cooking





Change in Magnetic Flux (Φ) ← scalar no direction

(磁通量)

$$\Phi = B_{\perp} \cdot A = BA \cos \theta \quad \text{Unit Wb (weber)}$$

$$1 \text{ Wb} = 1 \text{ T m}^2$$



$$B = \frac{\Phi}{A_{\perp}} \quad \text{Unit T (Tesla)}$$

$$1 \text{ T} = 1 \text{ Wb m}^{-2}$$

Faraday's Law (equation)

$$\Sigma = \frac{\Delta \Phi}{\Delta t}$$


↑
emf

Flux Linkage (Coil with N turns) ← scalar

$$\Sigma = N \frac{\Delta \Phi}{\Delta t} = \frac{\Delta (N\Phi)}{\Delta t} \quad N\Phi : \text{flux linkage}$$

Lenz's Law (for magnetic flux)

* an induced current always flow in a direction so as to oppose the change in magnetic flux that produces it.




$$\frac{V_s}{V_p} = \frac{N_s}{N_p}$$

No of turns of secondary coil

↑
no of turns of primary coil

Voltag ratio = turns ratio

Step Up and Step Down Transformers





Efficiency of a transformer $\eta = \frac{\text{useful output}}{\text{input}} \times 100\%$

ideal transformer
 $\eta = 100\%$


secondary side $I_s V_s = \eta \times I_p V_p$ Primary Side

Non-Ideal transformer

1. Heating of Coil Wire
2. Magnetization + Demagnetization of core
3. Flux Leakage
4. Eddy Current



Power loss during transmission



Transmission loss if current is 1000 A, and transmission line is 10 km


$$\text{resistance} = 1\Omega\text{km}^{-1} \times 2 \times 10\text{ km} = 20\Omega$$

$$\begin{aligned} \text{power loss} &= I^2 R \\ &= 1000 \times 1000 \times 20\Omega \\ &= 20,000,000\text{ W} \\ &= \underline{\underline{20\text{ MW}}} \end{aligned}$$

To reduce loss, we need to reduce I

$W = IV$ for the same power (W) $\Rightarrow V \uparrow$ (increase), $I \downarrow$ (decrease)

Hong Kong power transmission



* High Voltage reduce power loss

* ac is used, because it can easily step up and down by transformer

